

1/61




**SUBSTITUTE SHEET (RULE 26)** 

BEST AVAILABLE COPY



10/540991



10/540991

4/61







FIG. 2K



10/540991







**SUBSTITUTE SHEET (RULE 26)** 

PCT/IIS2003/041853


10/540991





9/61



**SUBSTITUTE SHEET (RULE 26)** 











WO 2004/060173


PCT/US2003/041853












10/540991



15/61






FIG. 5B








בוני צ

16/61










WO 2004/060173

PCT/US2003/041853

10/540991



10/540991

18/61





FIG. 64



20/61




FIG. 8B




FIG. 8A








FIG. 8


10/540991


















10/540991









24/61




10/540991








10/540991



PCT/US2003/041853 10/540991







31/61




FIG. 15






FIG. 15A





102

FIG. 16A

10/540991




FIG. 17




FIG. 17A




FIG. 18








FIG. 18A

10/540991













10/540991



10/540991







10/540991





FIG. 24

10/540991











FIG. 26























工事政務。

10/540991





10/540991






10/540991










10/540991


52/61


Standard Balling





























FIG. 45






FIG. 46


10/540991




752 761 759 759 750 750 753 FIG. 46B

10/540991







## This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

## IMAGES ARE BEST AVAILABLE COPY.

OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.